



Subject: Revision of Standard Road Plan Manual

Revision Date: 10/21/2025

To: Holders of Standard Road Plans

From: Design Bureau

The following revisions are effective with the 10/21/2025 letting. Projects let prior to this date may reference earlier versions of these Standard Road Plans. Questions concerning information contained on the Standard Road Plans should be directed to the Methods Section, Design Bureau, telephone (515) 239-1830 or email michael.thiel@iowadot.us.

| Standard Road Plan | Description of Revision |
|--------------------|-------------------------|
|--------------------|-------------------------|

BA Index

BA-250

Changed variable flare from 12:1 to 15:1. Added note 5.

BA-251

Changed variable flare from 12:1 to 15:1. Added note 3.

BA-252

Changed variable flare from 12:1 to 15:1. Added note 4.

BA-260

Changed variable flare from 12:1 to 15:1. Added note 4.

BR Index

BR-101

Changed "fabric" to "polymer grid" in circle note ten.

BR-201

Changed 'KS-2' joint to 'BT-2' joint.

BR-202

Changed 'KS-2' joint to 'BT-2' joint.

BR-203

Changed 'KS-2' joint to 'BT-2' joint.

BR-204

Changed 'KS-2' joint to 'BT-2' joint.

BR-205

Changed 'KS-2' joint to 'BT-2' joint.

BR-211

Changed 'KS-2' joint to 'BT-2' joint.

BR-212

Changed 'KS-2' joint to 'BT-2' joint.

BR-231

Changed 'KS-2' joint to 'BT-2' joint.

BR-241

Changed 'KS-2' joint to 'BT-2' joint.

DR Index

DR-502

Added reference to grate materials and galvanization.

LI Index

LI-103

Updated Sudas and IDOT Logos.

MI Index

MI-210

Changed 'K' joint to 'E" joint in circle note 2.

MI-221

Updated Sudas and IDOT Logos.

PR Index

PR-101

Removed 'KT-2' joint option.

PR-102

Removed 'KT-2' joint option.

PR-103

Removed 'KT-2' joint option.

PR-104

Removed 'KT-2' joint option.

PR-105

Removed 'KT-2' joint option.

PV Index

PV-101

Updated Sudas and IDOT Logos.

PV-102

Updated Sudas and IDOT Logos.

PV-103
Updated Sudas and IDOT Logos.

PV-104
Updated Sudas and IDOT Logos.

PV-121
Updated Sudas and IDOT Logos.

PV-201
Updated Sudas and IDOT Logos.

PV-410
Removed 'KT-2' joint option.

PV-411
Removed 'KT-2' joint option.

PV-412
Removed 'KT-2' joint option.

PV-414
Removed 'KT-2' joint option.

PV-500
Changed 'KT-2' joint to 'BT-2' joint.

PV-501
Changed 'KT-2' joint to 'BT-2' joint.

PV-502
Changed 'KT-2' joint to 'BT-2' joint.

PV-503
Changed 'KT-2' joint to 'BT-2' joint.

PV-504
Changed 'KT-2' joint to 'BT-2' joint.

PV-505
Changed 'KT-2' joint to 'BT-2' joint.

PV-506
Changed 'KT-2' joint to 'BT-2' joint.

PV-507
Changed 'KT-2' joint to 'BT-2' joint.

PV-508
Changed 'KT-2' joint to 'BT-2' joint.

PV-509
Changed 'KT-2' joint to 'BT-2' joint.

- PV-510**
Changed 'KT-2' joint to 'BT-2' joint.
- PV-511**
Changed 'KT-2' joint to 'BT-2' joint.
- PV-512**
Changed 'KT-2' joint to 'BT-2' joint.
- PV-513**
Changed 'KT-2' joint to 'BT-2' joint.
- PV-514**
Changed 'KT-2' joint to 'BT-2' joint.

SW Index

- SW-101**
Updated Sudas and IDOT Logos.
- SW-102**
Updated Sudas and IDOT Logos.
- SW-103**
Updated Sudas and IDOT Logos.
- SW-104**
Updated Sudas and IDOT Logos.
- SW-105**
Updated Sudas and IDOT Logos.
- SW-201**
Updated Sudas and IDOT Logos.
- SW-202**
Updated Sudas and IDOT Logos.
- SW-203**
Updated Sudas and IDOT Logos.
- SW-211**
Updated Sudas and IDOT Logos.
- SW-301**
Updated Sudas and IDOT Logos.
- SW-302**
Updated Sudas and IDOT Logos.
- SW-303**
Updated Sudas and IDOT Logos.

SW-304
Updated Sudas and IDOT Logos.

SW-305
Updated Sudas and IDOT Logos.

SW-307
Updated Sudas and IDOT Logos.

SW-308
Updated Sudas and IDOT Logos.

SW-401
Updated Sudas and IDOT Logos.

SW-402
Updated Sudas and IDOT Logos.

SW-403
Updated Sudas and IDOT Logos.

SW-404
Updated Sudas and IDOT Logos.

SW-405
Updated Sudas and IDOT Logos.

SW-406
Updated Sudas and IDOT Logos.

SW-501
Updated Sudas and IDOT Logos.

SW-502
Updated Sudas and IDOT Logos.

SW-503
Updated Sudas and IDOT Logos.

SW-504
Updated Sudas and IDOT Logos.

SW-505
Updated Sudas and IDOT Logos.

SW-506
Updated Sudas and IDOT Logos.

SW-507
Updated Sudas and IDOT Logos.

SW-508
Updated Sudas and IDOT Logos.

SW-509
Updated Sudas and IDOT Logos.

SW-510
Updated Sudas and IDOT Logos.

SW-511
Updated Sudas and IDOT Logos.

SW-512
Updated Sudas and IDOT Logos.

SW-513
Updated Sudas and IDOT Logos.

SW-514
Updated Sudas and IDOT Logos.

SW-515
Updated Sudas and IDOT Logos.

SW-516
Updated Sudas and IDOT Logos.

SW-521
Updated Sudas and IDOT Logos.

SW-538
Removed 'KT-2' joint option.

SW-539
Removed 'KT-2' joint option.

SW-541
Updated Sudas and IDOT Logos.

SW-542
Updated Sudas and IDOT Logos.

SW-545
Updated Sudas and IDOT Logos.

SW-601
Updated Sudas and IDOT Logos.

SW-602
Updated Sudas and IDOT Logos.

SW-603
Updated Sudas and IDOT Logos.

SW-604
Updated Sudas and IDOT Logos.

TC Index

TC-061

Added note 11, and added raised pavement markings.

TC-217

Added detail A, and adjusted all red times.

TC-252

Added sheet 4, closure of turn lanes.

TC-421

Adjusted taper width and length. Adjusted sign layout.

TS Index

TS-102

Updated Sudas and IDOT Logos.

WM Index

WM-101

Updated Sudas and IDOT Logos.

WM-102

Updated Sudas and IDOT Logos.

WM-201

Updated Sudas and IDOT Logos.